



fourstargroup



MODEL: 11220930

**COAT RACK**

## PARTS LIST AND HARDWARE

A. Upper spindle 1PC



B. Top hanger 6PCS



C. Middle hanger 3PCS



D. Middle spindle 1PC



E. Lower spindle 1PC



F. Leg 3PCS



G. Finial 1PC



## ASSEMBLY INSTRUCTIONS


### STEP 1

Slide the legs (F) into slots on the lower spindle (E), turning the finial (G) clockwise to secure the legs (F).




### STEP: 2

Attach the middle spindle (D) to lower spindle (E), turning clockwise, as shown. Then attach the upper spindle (A) to middle spindle (D), turning clockwise, as shown.



### STEP 3

Attach the top hanger (B) to upper spindle (A) and middle hanger (C) to middle spindle (D), turning clockwise, as shown.



Do you have any questions? Missing small parts or hardware?  
If you need assistance with the assembly of your **COAT RACK** please e-mail our Customer Service Department at:  
[support@fourstari.com](mailto:support@fourstari.com)  
or call us at (508) 435-4830  
or (800) 639-3803

Please include the following information in your email:

- Where item was purchased
- Item, model, style or SKU number listed on instructions or box
- Part number, description of the part and quantity needed

This information will help us get the proper part to you faster